

**Koordinātu tabula**

<b>Punkts Nr.</b>	<b>Koordinates LKS-92</b>	<b>Dziļums m</b>
1	x=352143 08; y=365321 37	-7,3
2	x=352135 92; y=365324 92	-9,2
3	x=352139 51; y=365332 06	-10,0
4	x=352146 66; y=365328 51	-8,0
5	x=352140 63; y=365316 54	-11,0
6	x= 352139 18; y=365309 37	-11,7
7	x=352132 50; y=365312 19	-12,0
8	x=352136 79; y=365315 18	-11,5
9	x=352144 55; y=365322 55	-10,5
10	x=352142 64; y=365312 60	-11,6
11	x=352151 26; y=365313 12	-8,0
12	x=352146 52; y=365314 69	-11,3
13	x=352132 97; y=365321 99	-11,0
14	x=352123 04; y=365334 75	-7,7
15	x=352117 97; y=365342 65	-6,8
16	x=352113 31; y=365347 03	-6,1
17	x=352108 44; y=365348 51	-5,5

SIA "Nord 57" ūdenslīdzēju darbu vadītājs:



D. Lapins