

















Test no: 3	Position: X: 0.00, Y: 0.00	Ground level: 0.00
Client: SIA Baltex Group	Date: 2016.06.15	Scale: 1 : 50
Project: Ventspils ATP	Page: 2/2	Fig:
		File: Ventspils 3.CPT









































